

FIG. 1A

↓
FLIP
↓




FIG. 1B

↓
GRIND
↓




FIG. 1C

↓
ETCH AND POLISH
↓




FIG. 1D





FIG. 1E




FIG. 1F




FIG. 1G




FIG. 2A

↓
FLIP
↓




FIG. 2B

↓
SILICON BOND
↓




FIG. 2D

↓
TO FIG. 2F

FIG. 2E





FIG. 2C



FROM 2E



ETCH




FIG. 2F



FLIP




FIG. 2G



SHEAR




FIG. 2H



ETCH AND POLISH





FIG. 3A

↓
FLIP
↓




FIG. 3B

↓
SILICON BOND
↓




FIG. 3E

↓
TO FIG. 3F




FIG. 3C


FIG. 3D




FROM 3E



FLIP



SHEAR



ETCH AND POLISH




FIG. 3F

FIG. 3G

FIG. 3H





FIG. 3I




FIG. 3J